

CHEM-E6160 FUNDAMENTALS OF PYROMETALLURGY

ONLINE-EXAM 21.12.2021, 09:00-13:00 (14:00 if you have a permission to one additional hour)

Use of course material in the exam is allowed.

Name:

Student no.

Theory questions (Write your answer directly below the question)

1. Pyrometallurgical furnaces have a crucial task in keeping the high temperature melts (slags, mattes, metals) and hot gases safely inside them. What are the main factors, and their roles, determining furnace integrity?

2. Metallurgical slags: a) their roles/tasks in metals production, b) their physico-chemical properties and factors determining those, c) differences in different metals' processes?

3. Examine factors that affect the final impurity concentrations of low-alloy steel.

Calculations (choose two out of the three!)

Calculations can be made directly to an excel file (found in the same place than the exam paper).

4. Steel production

The metallic charge of converter process consists of hot metal and scrap in the ratio of 4:1 (i.e., four times more hot metal than scrap). The hot metal contains 4 wt-% C, 1 wt-% Si and rest Fe. The scrap is assumed to be pure iron.

Oxygen of 99.5 % purity is blown for refining and the efficiency of oxygen utilization is 90 %. 2 wt-% of Fe charged is lost in the slag as FeO.

Steel contain 0.2 wt-% C and rest Fe. The rest of the carbon is distributed equally to CO (g) and CO₂ (g)

Calculate the following per ton of steel:

a) *Weights of hot metal and scrap to be charged (kg/t steel)*

b) *Oxygen to be blown (m³/t steel)*

(assume that the oxygen behaves ideally)

Chemical reactions:



$$M_{\text{Si}} = 28.086 \quad M_{\text{Fe}} = 55.845 \quad M_{\text{O}} = 15.999 \quad M_{\text{C}} = 12.011 \quad (\text{g/mol})$$

$$V_m = 22.414 \text{ l/mol} \quad (\text{molar volume of ideal gas})$$

5. Copper converting

Liquid matte (82 wt-% Cu₂S, 18 wt-% FeS) from the smelting process is oxidized in a Peirce-Smith converter by blowing oxygen-enriched air (29 vol-% O₂ in blast).

Converting takes place in two stages:

The first stage is the slag-forming stage where FeS is oxidized to FeO and SO₂ (g). Silica flux is added to form a liquid slag with FeO. The slag forming stage is finished when the FeS-content in the matte has been lowered to 1 wt-%.

Calculate

a) *The amount of oxygen-enriched air required for slag-forming stage per ton of matte (m³/t matte).*

(assume that the air behaves ideally)

b) *How much you need to charge silica flux (kg/t matte) to keep the fluxing ratio, SiO₂/Fe, in the slag at 0.5?*

Flux composition: 88 wt-% SiO₂, 6 wt-% Al₂O₃, 3 wt-% K₂O, 3-wt-% Na₂O

$$M_{\text{Cu}} = 63.546 \quad M_{\text{Fe}} = 55.845 \quad M_{\text{S}} = 32.065 \quad M_{\text{O}} = 15.999 \quad (\text{g/mol})$$

$$V_m = 22.414 \text{ l/mol} \quad (\text{molar volume of ideal gas})$$

6. Heat transfer

A furnace wall consists of three layers; a 20-cm inner layer of refractory lining (thermal conductivity 4.2 W/m·K), a 10-cm intermediate layer of insulating brick (thermal conductivity 0.3 W/m·K) and a 1-cm steel shell (thermal conductivity 40 W/m·K). The heat loss from the steel plate to the atmosphere can be represented by a combined heat transfer coefficient for convection and radiation of 13.8 W/m²·K. The temperature inside the furnace is 1420°C and the atmospheric temperature 23°C. The internal surface temperature of the inner refractory layer stays in a constant freeze lining temperature of 1180°C.

Calculate

a) *The heat loss per unit surface area*

b) *The in & out surface temperatures of the layers.*